QUALITY CONTROL

BR No: 221 A/20/08/19

Name of the Work: Development of Park and Play Ground at Siddarthanagara in W. NO 16 R.R. Nagara Zone.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed one years back.

Assistant Executive Engineer
Rajarajeshwari Nagar(Project)
Bruhat Bengaluru Mahanagara Palike

Executive Engineer (Project)
Rajajeshwari Nagar Zone
Bruhat Bengaluru Mahanagara Palike